






# IRONY BASE HEADBOARD (100-120)<sup>-V07</sup>



ASSEMBLY INSTRUCTION-1 (for metal base)



Accessory	A	B	C	D	E	F	G	H	Tools Needed
Quantity	4	4	4	4	4	4	1	4	

# IRONY BASE HEADBOARD (100-120)<sup>-V07</sup>

ASSEMBLY INSTRUCTION-2 (for metal base)



for panel base

for panel base

Accessory	A	B	C	D	E	F	G	H	Tools Needed
Quantity	4	4	4	4	4	4	1	4	